



Occupational Safety and Health Administration

Inspection Number	1. Photo ID No.	2. Date/Time	3. Citation Number	4. Item Number	5. Instance No.
1148200	8962,8963,8967, 8973	5/25/16	1	1	1



OSHA-89

These photos were taken by CSHO on 5/25/2016. Please refer to CSHO diagram on the locations of the straps/shackles on how they were attached to the mobile equipment during the accident.